

Gawler
Sunday 22nd May 2016

Weather Condition: OVERCAST

Track Condition: GOOD

Abandonment of the Meeting

The Lure driver at inspection time reported that the Lure was losing power in a couple of areas of the track and therefore not operating correctly. The course electrician and head of industry maintenance attended Gawler. Work and tests continued until 7.00pm when it was reported that the problem was still not able to be identified. Therefore the remainder of the meeting was abandoned.

